



Tamil Nadu Electricity Board Engineers' Sangam

தமிழ்நாடு மின்சார வாரிய பொறியாளர் சங்கம்

Regd. No. 124/MDS (Recognised)

(Affiliated to All India Federation of Power Diploma Engineers)

144, Electricity Avenue, Anna Salai, Chennai - 600 002.

44, Ramasamy Garden Street, Royapetah, Chennai - 600 014

Phone : 28521968, E-mail : tnebes@yahoo.co.in

PRESIDENT

Er. A. ANTONYPADOVARAJ

GENERAL SECRETARY

Er. V. ASHOKKUMAR

TREASURER

Er. R. BADRINARAYANAN

To

THE MANAGING DIRECTOR,
TANTRANSCO,
Chennai-600 002.

THE DIRECTOR / DISTRIBUTION,
TANGEDCO,
Chennai-600 002.

Lr.No.GS/TNEBES/F10/ D57 /2015,Dt.08.12.2015.

Sir,

Sub: TANTRANSCO and TANGEDCO Offices accommodated in Guindy Complex – water logged – records, equipments, vehicles and furnitures heavily damaged – urgent action – requested – Reg.

The following Offices;

the Chief Engineer / Transmission Project-I / Chennai ,
the Superintending Engineers / CDC-I / TANTRANSCO
the Superintending Engineers / CDC-II / TANTRANSCO
the Superintending Engineer / GCC-I / TANTRANSCO
the Superintending Engineer / GCC-II / TANTRANSCO and
the Superintending Engineer / CDC/ TANGEDCO are
accommodated in the Guindy Complex.

There is no permanent building for the above offices. Instead the offices are allowed to function in a temporary go down without proper infrastructure.

In the recent floods, the above offices were marooned with flood water up to the level of nearly 8 foot. The records, furnitures, vehicles and equipments like computers, printers, Xerox machines, laptops were heavily damaged and most of them could not be used again.

Special attention has to be paid to clean the office complex and to dry the records which can be retrieved. Otherwise running of the offices and carrying out normal / routine works are very difficult. Any delay in restoration will further increase the damage and losses.

Tamil Nadu Electricity Board Engineers' Sangam

We learn that, the 230 KV Guindy Sub-station was commissioned on 16.04.2015. The 3rd and 4th floors of the above Sub-station which was vacant for the past 8 months was not occupied by the offices accommodated in the Guindy complex due to non electrification of the above floors.

If proper attention was paid in time on the electrification, the offices could have been shifted to the Sub-station and the extensive damage could have been avoided.

To bail out from the present crisis, we suggest as follows;

- Required fund under flood relief / temporary advance may be sanctioned immediately to set right the damages caused due to the floods at Guindy complex.
- Required heaters / Hot air blowers are to be purchased to dry the records which got damaged in the flood water.
- The electrification for the 3rd and 4th floors of 230 KV Guindy SS has to be done, at least now, on war footing and the offices of TANTRANSCO are to be shifted to 3rd and 4th floors of the 230 KV Guindy SS.
- The offices of TANGEDCO may be shifted to TANGEDCO buildings (or) 230 KV Alandur SS.
- All damaged furniture's and equipments like computers, Lap tops, Xerox machine and printers etc., are to be purchased and supplied with immediate effect.
- Computers to be supplied to all Engineers working in CDC and GCC.
- Parking sheds to be constructed at the 230 KV Guindy SS for parking the vehicles of Staff and Office.

We request the personal attention of the Managing Director / TANTRANSCO and the Director / Distribution / TANGEDCO on our representation for early and permanent solution.

Thanking you, Sir,

Yours sincerely,

(V. ASHOK KUMAR)
General Secretary.

Copy to:

The Director / Transmission Project / Chennai.

The Chief Engineer / Distribution / Chennai / North Region.

The Chief Engineer / Transmission Project-I / Chennai.

The Superintending Engineer / CDC / CDC-I / CDC-II / GCC-I / GCC-II.